

Parts for Sale

Model 34C parts: Water pump, new and complete, \$1,500; Water pump casting (not machined) \$900; Other water pump parts available. Air pump handle, \$35; Oil sight gauge, \$37; Cam shaft, new, \$2,400, used \$150 each; Brake drums, new cast iron, not machined, \$550; two engine blocks, crankcase pan, and misc.parts. Contact Walker Woolever, Aptos, CA, 831-688-1816

Model 78 parts. Two engines, one runs, one in parts; 2 transmissions, 2 sets brake pedals, clutch and pressure plates; 2 radiators, radiator shell, lightning bolt. 2 brake drums, 4 carburetors, 4 starters, 2 real axle shafts, gas tank, headlights, head light lenses, brake light, hubcaps, hood, fender, wrist pins, head gaskets, scuff plates, wiring harness, many others. Package deal, \$5,000 US. Contact Neil Ozad, Windsor, ON 519-992-1615

Model 78 Engine and transmission, no. N5588. The motor appears to be mostly complete, missing the carburetor and starter. The motor is assembled, and includes parts of the brake and clutch pedal assemblies. It does NOT turn. Photos on request, located in North Ogden, Utah. Contact Terry Haines, 801-430-8630, or you can email to terryh0432@yahoo.com

1931 Model 70 Engine, U2843X. Complete with carburetor, starter, and distributor. Turns freely, always stored under cover. Contact ricerd013@outlook.com

Solid Metal Automobile Trunk. 37" x 15" x 18" high. Asking \$700. Contact Calvin High, 717-951-7469

Old Marmon Club Directories: 1970, 1972, 1982, 2000, 2001, 2002, and 2003. Free, post paid. Contact Erica DeBord, executive assistant to Chris MacAllister, ericadebord@macallister.com

Parts Wanted

For 1919 Model 34 7-passenger touring: Aluminum engine block, rear axle, and a radiator for a near original Model 34. Contact Paul LeFoulon, polefoulon@gmail.com

For 1920 Model 34 7-passenger Touring: Original headlights and crossbar; trouble light (as shown in the "tools" section of the manual); Sales Brochure, and any other 1920 Marmon literature. Contact David Peeler, 704-564-5468, or dpeeler6@gmail.com

For 1922 Model 34B 4-passenger Touring: Shifter, brake lever and base assembly; right front hub (LH threads) for a Hayes wire wheel. Please contact Andrew Straw at 828-855-5887, or akstraw@icloud.com.

For 1929-1930 Roosevelt: A radiator cap to replace the one I lost! An original, or one from any other model that will fit; also the heat exchanger that fits above the Roosevelt carburetor. Please contact Ken Endter, kenendter@sbcglobal.net, or 760-685-7703

For 1930 Marmon-Roosevelt: The steering column base horn & light switch; replacement carburetor. Contact Bill Nielsen in Australia, 61-0468589270, or billnielsen@bigpond.com

For 1931 Marmon Sixteen: Brake drums needed for a newly-acquired 1931 Sixteen Victoria. Will purchase; have some spare parts available to trade. Contact Jim Hussey, 510-614-3500, or 510-614-4583